

---

**FA-300, FA-300-6L, FR-320, FX-350, FX-351, UDACT-300A and DTC-300A  
Hardware Upgrade (ECO-07-161)**

The DC telephone line detection circuit has been upgraded to prevent nuisance DC line fail trouble. The circuit will now detect DC line fail if the voltage falls below 21Volts.

The PC Board revisions have been changed as follows:

- FA-300-6DDR MD-731 changed from Rev. L to Rev. M
- FA-300-6LDR/W MD-814 changed from Rev. G to Rev. H
- FA-301-12DDR MD-744 changed from Rev. L to Rev. M
- FA-301-12LDR/W MD-745 changed from Rev. M to Rev. N
- FA-301-8LDW MD-797 changed from Rev. K to Rev. L
- FR-320-DR/W MD-877 changed from Rev. B to Rev. C
- FX-350-DR MD-815 changed from Rev. H to Rev. I
- FX-351-LDW MD-843 changed from Rev. D to Rev. E
- UDACT-300A MD-802 changed from Rev. E to Rev. F
- DTC-300A MD-808 changed from Rev. E to Rev. F

Systems without Dialers are not affected with these changes.

All new builds and those currently in stock have been upgraded with the above changes.

If you have any questions or concerns, please contact the Technical Support Department.