

TAS-2000 Firmware Upgrade (ECO-06-185 & 07-010)

The TAS-2000 lobby panel firmware has been upgraded from **version 2.0.4** to **version 2.0.5**. The following are the changes and enhancements that were made:

- In the previous firmware version, there's been a problem with memory loss of residents names, telephone number etc. This upgrade adds enhanced memory protection to prevent memory loss.

The 2008M NSL controller firmware has been upgraded from **version 1.0.7** to **version 1.0.9**. The following are the changes and enhancements that were made:

- In the previous version, when a call was initiated from the lobby and the call was pick-up by the resident, the ring tone continued to sound until the ring tone cycle was completed. This new firmware corrects this problem.
- In the previous version, if the resident was talking to a visitor and an outside call was received, the call-waiting feature was cutting out the visitor. This new firmware corrects this problem.

All new builds and those currently in stock have been upgraded with the new firmware.

If you have any questions or concerns regarding these changes, please contact the Technical Support Department.