

2008M Relay Cabinet Control Board MD-586

The 2008M relay cabinet control board MD-856 firmware has been upgraded from **version 1.0.10** to **version 1.0.11**. The following are the changes and enhancements that were made:

- Corrected the problem where the NSL system would disconnect (hang-up) when a call is initiated from the lobby panel after or during the first ring when 5 or more telephones are connected in the suite.

All new builds and those currently in stock have been upgraded with the above changes.

If you have any questions or concerns, please contact the Technical Support Department.