
UDACT-300A / DTC-300A Firmware Upgrade (ECO-07-145)

The UDACT-300A / DTC-300A dialer firmware has been upgraded from **version 1.0.2 to 1.1.1**. The following are the changes and enhancements that were made:

- The telephone line DC voltage supervision time has been increased to improve the line supervision and prevent false trouble reporting.
- Increased the receive gain of the dialer to improve the Kiss-Off tone detect.
- The Kiss-Off detect waiting period was increased on the Contact ID protocol to prevent the dialer from missing the Kiss-Off tone from the receiver.
- Corrected the problem where the dialer did not report the zones properly after 255 zones.
- Changed the LCD description on the dialer from "Waiting for ACKtone" to "Waiting handshake"

The new firmware can be programmed into existing dialers using the MSW-017 Firmware Upgrade Utility Program version 1.0.3.

The new firmware file is available on the Mircom website; Public download section.

If you have any questions or concerns, please contact the Technical Support Department.