

FX-350 Configurator Upgrade (ECO-08-50)

The FX-350 configurator program has been upgraded from **version 2.4.14 to 2.4.15**. The following are the changes and enhancements that were made:

- Added serial ports **COM 9 – COM 20** to the “**User Preferences**” dialog.
- In the previous version, if the installer was using Windows Vista with Service Pack 1 (SP1) installed on the computer, an error message “**Database error in DOA.Field**” was displayed when a new job was created. This problem was corrected with the new configurator.

The new firmware file is available on the Mircom website www.mircom.com ESD section.

If you have any questions or concerns, please contact the Technical Support Department.