

FX-2000 Configurator Upgrade

The FX-2000 configurator program has been upgraded from **version 2.3.14** to **2.3.15**. The following are the changes and enhancements that were made:

- The previous FX-2000 Configurator version 2.3.14 may display an error message “**Device parameters do not correspond to any known parameter type (in [SYSDevParams])**” when retrieving an existing job from a panel that was not created with version 2.3.14. This problem was corrected with the new configurator version 2.3.15

The new configurator is available on the Mircom website www.mircom.com ESD section.

If you have any questions or concerns, please contact the Technical Support Department.