

**Mircom MIX-1251B, MIX-1251BA, System Sensor 1251B and 1251BA**

An issue with the System Sensor 1251B and 1251BA, and the Mircom MIX -1251B and MIX-1251BA addressable ionization type smoke detectors has been identified. This issue will cause a small number of detectors to report a nuisance level too low condition. The detectors were manufactured between March 2008 and October 2008. This will not prevent the detectors from detecting smoke and will not prevent the fire alarm panel from operating properly.

Any detector that is not being reported as level too low can be left in place.

Affected detectors can be identified by the date code below the bar code on the label. The range of the date codes is from 8031 to 8105. If there are 6 digits, the first four are the date code.

Any detectors that cause a level too low should be replaced. For detectors that are in this date range, please contact Customer Service at 1-888-MIRCOM5 (1-888-647-2665) for further details.

If you have any questions or concerns, please contact the Technical Support Department.